



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	DE/BVS/QAR14.0001/10	Page 1 of 1																		
QAR Free Ref. No.:	ZQS/E371/25	Status: Issued																		
Details of change:	No changes.	Date of issue: 2025-11-21																		
Location(s) audited:	PARAT Solutions GmbH Gewerbegebiet Manzing 7 94065 Waldkirchen Germany	Valid until: 2028-12-19 Audit date: 2025-10-22																		
Issuing ExCB:	BVS - DEKRA Testing and Certification GmbH																			
Manufacturer:	PARAT Solutions GmbH Gewerbegebiet Manzing 7 94065 Waldkirchen																			
Location of Manufacturer:	Germany																			
Product information:	Manufacture of torch lights																			
Type of protection:	Intrinsic safety "i" Optical radiation "op is/pr/sh"																			
Related QARs:	<table><tbody><tr><td>DE/BVS/QAR14.0001/00</td><td>DE/BVS/QAR14.0001/01</td><td>DE/BVS/QAR14.0001/02</td></tr><tr><td>DE/BVS/QAR14.0001/03</td><td>DE/BVS/QAR14.0001/04</td><td>DE/BVS/QAR14.0001/05</td></tr><tr><td>DE/BVS/QAR14.0001/06</td><td>DE/BVS/QAR14.0001/07</td><td>DE/BVS/QAR14.0001/08</td></tr><tr><td>DE/BVS/QAR14.0001/09</td><td></td><td></td></tr></tbody></table>		DE/BVS/QAR14.0001/00	DE/BVS/QAR14.0001/01	DE/BVS/QAR14.0001/02	DE/BVS/QAR14.0001/03	DE/BVS/QAR14.0001/04	DE/BVS/QAR14.0001/05	DE/BVS/QAR14.0001/06	DE/BVS/QAR14.0001/07	DE/BVS/QAR14.0001/08	DE/BVS/QAR14.0001/09								
DE/BVS/QAR14.0001/00	DE/BVS/QAR14.0001/01	DE/BVS/QAR14.0001/02																		
DE/BVS/QAR14.0001/03	DE/BVS/QAR14.0001/04	DE/BVS/QAR14.0001/05																		
DE/BVS/QAR14.0001/06	DE/BVS/QAR14.0001/07	DE/BVS/QAR14.0001/08																		
DE/BVS/QAR14.0001/09																				
Related Certificates (manual insertion)::																				
Related Certificates (automatic linking)::																				
Related Certificates for previous versions:	<table><tbody><tr><td>IECEx BVS 12.0043X issue: 1</td><td>IECEx BVS 12.0043X issue: 2</td><td>IECEx BVS 12.0043X issue: 3</td></tr><tr><td>IECEx BVS 12.0044X issue: 2</td><td>IECEx BVS 12.0044X issue: 3</td><td>IECEx BVS 12.0044X issue: 4</td></tr><tr><td>IECEx BVS 13.0034X issue: 1</td><td>IECEx BVS 13.0034X issue: 2</td><td>IECEx BVS 13.0034X issue: 3</td></tr><tr><td>IECEx BVS 13.0034X issue: 4</td><td>IECEx BVS 13.0057X issue: 1</td><td>IECEx BVS 13.0057X issue: 2</td></tr><tr><td>IECEx BVS 13.0057X issue: 3</td><td>IECEx BVS 19.0049X issue: 0</td><td>IECEx BVS 19.0049X issue: 1</td></tr><tr><td>IECEx BVS 19.0049X issue: 2</td><td></td><td></td></tr></tbody></table>		IECEx BVS 12.0043X issue: 1	IECEx BVS 12.0043X issue: 2	IECEx BVS 12.0043X issue: 3	IECEx BVS 12.0044X issue: 2	IECEx BVS 12.0044X issue: 3	IECEx BVS 12.0044X issue: 4	IECEx BVS 13.0034X issue: 1	IECEx BVS 13.0034X issue: 2	IECEx BVS 13.0034X issue: 3	IECEx BVS 13.0034X issue: 4	IECEx BVS 13.0057X issue: 1	IECEx BVS 13.0057X issue: 2	IECEx BVS 13.0057X issue: 3	IECEx BVS 19.0049X issue: 0	IECEx BVS 19.0049X issue: 1	IECEx BVS 19.0049X issue: 2		
IECEx BVS 12.0043X issue: 1	IECEx BVS 12.0043X issue: 2	IECEx BVS 12.0043X issue: 3																		
IECEx BVS 12.0044X issue: 2	IECEx BVS 12.0044X issue: 3	IECEx BVS 12.0044X issue: 4																		
IECEx BVS 13.0034X issue: 1	IECEx BVS 13.0034X issue: 2	IECEx BVS 13.0034X issue: 3																		
IECEx BVS 13.0034X issue: 4	IECEx BVS 13.0057X issue: 1	IECEx BVS 13.0057X issue: 2																		
IECEx BVS 13.0057X issue: 3	IECEx BVS 19.0049X issue: 0	IECEx BVS 19.0049X issue: 1																		
IECEx BVS 19.0049X issue: 2																				
Comments:																				